-	Туре	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
<u> </u>	BRS	957	fpga same programmable same interconnect	USPAT; US-PGPUB; DERWENT	2003/09/15 08:50		
<u> </u>	BRS	245	fpga same programmable same interconnect and rows and columns and horizontal and vertical	USPAT; US-PGPUB; 2003/09/15 08:50	2003/09/15 08:50		
ш	BRS	149	fpga same programmable same interconnect and rows and columns and horizontal and vertical and interface	USPAT; US-PGPUB; 2003/09/15 08:55	2003/09/15 08:55		
ш	BRS	52	fpga same programmable same interconnect and rows and columns and USPAT; US-PGPUB; 2003/09/16 11:16 horizontal and vertical and interface and diagonal	USPAT; US-PGPUB; DERWENT	2003/09/16 11:16		
	BRS	0	freeway same gate same array	USPAT; US-PGPUB; DERWENT	2003/09/15 14:52		
ш	BRS	6	freeway same array and architecture	USPAT; US-PGPUB; 2003/09/16 11:19	2003/09/16 11:19		
	BRS	12	fpga same programmable same interconnect and rows and columns and horizontal and vertical and interface and diagonal and bitstream	USPAT; US-PGPUB; 2003/09/16 11:17 DERWENT	2003/09/16 11:17		
	BRS	0	freeway same array and architecture and bitstream	itecture and USPAT; US-PGPUB; DERWENT	2003/09/16 11:20		
	BRS	0	freeway same array and architecture and USPAT; US-PGPUB; netlist	USPAT; US-PGPUB; DERWENT	2003/09/16 11:20		
ш	BRS	0	freeway same netlist and routing	USPAT; US-PGPUB; 2003/09/16 11:20	2003/09/16 11:20		